

PARTS BOOK Butterfly single-head embroidery machine



- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

1、FRAME AND TABLE COMPONENTS			
DIAGRAM/PART	NAME		
1/1	MACHINE BRACKET		
1/2	MACHINE BRACKET CASE(FRONT RIGHT)		
1/3	MACHINE BRACKET CASE(FRONT LEFT)		
1/4	MACHINE BRACKET CASE(BACK RIGHT)		
1/5	MACHINE BRACKET CASE(BACK LEEFT)		
1/6	MACHINE CASE FIXING WASHER		
1/7	M4*8 SCREW		
1/8	4*6 SCREW		
1/9	STRECH FRAME SUPPORT		
1/10	SCREW		
1/11	TABLE WASHER		
1/12	3*20 SCREW		
1/13	CIRCLIP		
1/14	4*12 SCREW		
1/15	TABLE(UPPER)		
1/16	TABLE(LOWER)		
1/17	MACHINE FRAME		
1/18	M10 NUT		
1/19	M10 PLAIN WASHER		
1/20	M10*100 SCREW		
1/21	MACHINE BRACKET SUPPORT		
1/22	MACHINE FEET ANTISLIP WASHER		
1/23	POWER BOX TABLE		
1/24	PLAIN WASHER		
1/25	3*20 SCREW		
1/26	M12*45 SCREW		
1/27	M12 PLAIN WASHER		
1/28	M12 NUT		
1/29	MACHINE TRADEMARK		
1/30	M5*10 SCREW		
1/31	WHEEL ASM.		
1/32	M8*20 SCREW		
1/33	PLAIN WASHER		



- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

2. ROTARY HOOK BOX		3、THREAD CUT PARTS		
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME	
2/1	MACHINE TABLE	3/1	THREAD CUT MOTOR	
	ROTARY HOOK FRONT CUSHION	3/2	THREAD CUT MOTOR BRACKET	
2/3	ROTARY HOOK BACK CUSHION	3/3	THREAD CUT SENSOR	
2/4	MAIN MOTOR	3/4	M3*8 SCREW	
2/5	M8*30 SCREW	3/5	4*8 SCREW	
2/6	M8 SPRING WASHER	3/6	RUBBER WASHER	
2/7	M8 PLAIN WASHER	3/7	M4*8 SCREW	
2/8	MACHINE TABLE BUSHING	3/8	DRIVE ROD	
2/9	LOWER SHAFT	3/9	THREAD CUT SENSOR HEAD	
2/10	BEARING	3/10	M4*10 SCREW	
2/11	BEARING BUSHING	3/11	THREAD CUT PITMAN ROD	
2/12	5M*16φ7.94 LOWER SHAFT PULLEY	3/12	PIN	
2/13	SHAFT CONNECTION	3/13	THREAD CUT DRIVE CONNECTION LEVER	
2/14	M5*6 SCREW	3/14	COPPER BUSHING	
2/15	M4*4 SCREW	3/15	THREAD CUT LEVER	
2/16	M6*8 SCREW	3/16	FLAT EMBROIDERY PITMAN ROD	
2/17	M6*6 SCREW	3/17	DRIVE ROD	
2/18	M5*20 SCREW	3/18	FLEXIBLE KNIFE	
	ROTARY HOOK BOX COVER	3/19	M3*4 SCREW	
2/20	SCREW	3/20	SPRING WASHER	
2/21	ROTARY HOOK BOX BIG COVER	3/21	FIXED KNIFE	
2/22	4*8 SCREW	3/22	M3*3 SCREW	
2/23	NEEDLR PLATE(LOWER)	3/23	3*5 SCREW	
2/24	NEEDLE PLATE(UPPER)	3/24	POSITION CUSHION	
2/25	SCREW	3/25	THREAD PICK PITMAN ROD	
2/26	KNIFE SUPPORT/NEEDLE PLATE BRACKET	3/26	THREAD PICK ELECTROMAGNET ASM.	
2/27	ROTARY HOOK	3/27	THREAD PICK ELECTROMAGNET INSTAL BOARD	
2/28	ROTARY HOOK CASE	3/28	THREAD PICK RESET PLATE	
2/29	BOBBIN	3/29	3.3*3.0 SCREW	
2/30	ROTARY HOOK POSITION HOOK	3/30	φ3 OPEN CIRCLIP	
2/31	9/64 SCREW	3/31	2.5*4 SCREW	
2/32	3*16 PIN	3/32	PICK FEED BRACKET	
2/33	SCREW	3/33	THREAD PICK FORK	
2/34	ROTARY HOOK BOX GUARD	3/34	PIN	
2/35	4*6 SCREW	3/35	PLAIN WASHER	
		3/36	THREAD PICK FORK BRACKET	
		3/37	THREAD PICK THRUST BLOCK	
		3/38	M5*10 SCREW	
		3/39	M4 PIN	
		3/40	M4 NUT	
		3/41	THREAD PICK PIN	



- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

4、MACH	IINE HEAD		
DIAGRAM/PART	NAME		
4/1	MACHINE HEAD	4/31	ADJUSTING HANDLE
4/2	UPPER SHAFT BACK BEARING BUSHING	4/32	M4*4 SCREW
4/3	BEARING	4/33	ф7.94 SHAFT
1/4	M5*6 SCREW	4/34	SPRING
4/5	BEARING	4/35	ADJUSTING HANDLDE INSTAL BRACKET
4/6	SENSOR SUPPORT	4/36	M4*8 SCREW
4/7	4*6 SCREW	4/37	GEAR
4/8	UPPER SHAFT SENSOR	4/38	SM15/64*28 L=6 SCREW
4/9	M4*6 SCREW	4/39	THREAD TAKE-UP DRIVE CAM
4/10	M6*8 SCREW	4/40	SM15/64*28 L=4 SCREW
4/11	M6*6 SCREW	4/41	CRANKSHAFT
4/12	MACHINE HEAD SHADE WASHER	4/42	DOMESTIC CONECTION ROD
1/13	WINDING PLATE	4/43	NEEDLE BEARING
1/14	M4*8 SCREW	4/44	SCREW
4/15	M4 SPRING WASHER	4/45	M4*10 SCREW
4/16	M4 PLAIN WASHER	4/46	LOWER GUIDE RAIL POSITION HOOK
4/17	HTD5M-15-525 BLET	4/47	GUIDE ROD THRUST PLATE
4/18	UPPER SHAFT PULLEY	4/48	DUSTPROOF PLATE(LEFT)
4/19	M5*6 SCREW	4/49	DUSTPROOF PLATE(RIGHT)
4/20	6004φ15 BEARING BUSHING	4/50	NA4902 NEEDLE BEARING
4/21	6004 BEARING	4/51	GUIDE RAIL SLIDE BLOCK POSITION BRACKET
4/22	φ15 UPPER SHAFT	4/52	SIGHT GLASS
4/23	DIAL	4/53	DIAL FINGER
1/24	MACHINE HEAD GUIDE RAIL(9 NEEDLES)	4/54	M4*6 SCREW
1/24	MACHINE HEAD GUIDE RAIL(12 NEEDLES)	4/55	THRUST PLATE
1/25	M4*10 SCREW	4/56	THRUST PLATE SUPPORT
1/26	PRESSER FOOT CAM GUARD	4/57	MACHINE HEAD FRONT COVER
1/27	PRESSER FOOT DRIVE CAM	4/58	MACHINE HEAD BACK COVER
4/28	M8*8 SCREW	4/59	THREAD TENSION ASM.
1/29	M10*40 SCREW	4/60	M4*8 SCREW
4/30	M10 SPRING WASHER	4/61	SPOTLIGHT BRACKET
		4/62	SPOTLIGHT



- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

5 NEEDLE BAR DRIVE PARTS		6、 UPPER	6、 UPPER THREAD HOLDER SETS		
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME		
5/1	THREAD TAKE-UP DRIVE ROD B	6/1	UPPER THREAD MOTOR		
5/2	M4*10 SCREW	6/2	UPPER THREAD MOTOR BASE		
5/3	M8 PLAIN WASHER	6/3	M4*8 SCREW		
5/4	THREAD TAKE-UP ROD BEARING BRACKET	6/4	M4*6 SCREW		
5/5	M5 PLAIN WASHER	6/5	M4 SPRING WASHER		
5/6	M5 SPRING WASHER	6/6	M4 PLAIN WASHER		
5/7	M5*12 SCREW	6/7	UPPER THREAD SPRING		
5/8	THREAD TAKE-UP DRIVE ROD	6/8	3*6 SCREW		
5/9	CAM DRIVE ROD	6/9	M3*18 SCREW		
5/10	COPPER BUSHING	6/10	NUT		
5/11	DRIVE ROD	6/11	CONNECTION ROD		
5/12	PIN B	6/12	PIN		
5/13	PIN A	6/13	HOOK FIXING BLOCK		
5/14	SMALL CONECTION ROD	6/14	M4*10 SCREW		
5/15	M5 NUT	6/15	UPPER HOOK DRIVE ROD		
5/16	A DRIVE BEARING BUSHING	6/16	M3*10 SCREW		
5/17	φ10 OUTER CIRCLIP	6/17	ERASURE BLOCK		
5/18	DRIVE SHAFT UP-DOWM FLEXIBLE SUPPORT	6/18	M5*12 SCREW		
5/19	3*4 SCREW	6/19	M5 SPRING WASHER		
5/20	PRESSER FOOT SLIDE BLOCK ASM.	6/20	M5 PLAIN WASHER		
5/21	RUBBER SUPPORT(LARGE)	6/21	HOOK GUIDE BRACKET		
5/22	DRIVE BEARING BUSHING	6/22	M3 NUT		
5/23	WOOL TOP	6/23	UPPER HOOK SUPPORT		
5/24	φ7.24 MAIN SHAFT	6/24	ноок		
5/25	SPRING	6/25	3*4 SCREW		
5/26	689Z BEARING	6/26	M5*16 SCREW		
5/27	WOOL TOP	6/27	SUPPORT BUSHING		
5/28	M5*6 SCREW	6/28	HOOK GUIDE PLATE		
5/29	NEEDLE BAR DRIVE BLOCK ASM.	6/29	M4*8 SCREW		
57 = 5		6/30	M4*12 SCREW		
		6/31	JUMPING MOTOR INSTALL BRACKET		
		6/32	RUBBER WASHER		
		6/33	M3 PLAIN WASHER		
		6/34	M3*12 SCREW		
		6/35	JUMPING CONNECTION ROD SUPPORT		
		6/36	JUMPING CONNECTION ROD		
		6/37	4*6 SCREW		



- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

7、 COLOR CHANGE PARTS		8、 NEEDI	8、 NEEDLE BAR BRACKET(1)	
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME	
7/1	COLOR CHANGE MOTOR	8/1	NEEDLE BAR ASM.	
7/2	ADJUSTING HANDLE(SMALL)	8/2	M4*16 SCREW	
7/3	M4*6 SCREW	8/3	DB*K5 75/11 NEEDLE	
7/4	M4*8 SCREW			
7/5	M4 SPRING WASHER			
7/6	M4 PLAIN WASHER	9、 NEEDI	LE BAR BRACKET(2)	
 7/7	MOTOR SUPPORT	DIAGRAM/PART	NA NAT	
7/8	COLOR CHANGE MOTOR BRACKET	DIAGRAM/PART	NAME	
, 7/9	M5 PLAIN WASHER	9/1	9 NEEDLES LOWER THREAD GUIDE	
7/10	M5 SPRING WASHER	i .	12 NEEDLES LOWER THREAD GUIDE	
7/11	M5*12 SCREW		9/64 SCREW	
7/12	M4*8 SCREW	9/3	LOWER PLATE(9 NEEDLES)	
7/13	696LU(NSK) BEARING	9/3	LOWER PLATE(12 NEEDLES)	
7/14	696LUBEARING	9/4	MEDIAL THREAD GUIDE ASM.(9 NEEDLES)	
, 7/15	M3*8 SCREW	9/4	MEDIAL THREAD GUIDE ASM.(12 NEEDLES)	
7/16	COLOR CHANGE CAM		THREAD TENSION ASM.	
7/17	M3*5 SCREW		9/64 SCREW	
7/18	COLOR CHANGE SUPPORT		UPPER PLATE(9 NEEDLES)	
7/19	M4 NUT		UPPER PLATE(12 NEEDLES)	
7/20	POTENTIOMETER SUPPORT	9/8	ON-OFF ANNUNCIATOR SUPPORT	
7/21	M4*16 SCREW	9/9	4*6 SCREW	
, 7/22	PHOTO COUPLER SUPPORT	9/10	CUSHION	
7/23	COLOR CHANGE COPPER BUSHING	9/11	COLOR CHANGE ROLLAR ASM.(9 NEEDLES)	
7/24	COLOR CHANGE BOX CASE	9/11	COLOR CHANGE ROLLAR ASM.(12 NEEDLES)	
, 7/25	4*6 SCREW		M4*12 SCREW	
7/26	POTENTIOMETER	9/13	M4*18 SCREW	
		9/14	M4 NUT	
		9/15	GUARD SUPPORT	
		9/16	M4*8 SCREW	
		· ·	M4 SPRING WASHER	
			M4 PLAIN WASHER	
		9/19	DUSTPROOF CASE	
		<u>.</u>	MAGNET	
		9/21	M3*14 SCREW	
		9/22	M3 NUT	



10/43

10/44

10/45

10/46 10/47 M4*12 SCREW

RULER

X-AXIS LIMIT SENSOR

X-AXIS DRIVE BLET PLATE(UPPER)

Butterfly BUTTERFLY BRAND SINGLE HEAD MACHINE PARTS BOOK

- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

10、 X-AX	IS DRIVE PARTS	11、 Y-AX	(IS DRIVE PARTS
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME
10/1	X-AXIS GUIDE RAIL BRACKET	11/1	3m*33φ12 MAIN SHAFT DRIVE WHEEL
10/2	WOOL TOP	11/2	M4*6 SCREW
10/3	COVER SUPPORT	11/3	Y-AXIS MOTOR BRACKET
LO/4	X-AXIS DRIVE COVER	11/4	M6*16 SCREW
LO/5	X-AXIS DRIVE COVER	11/5	86 MOTOR
.0/6	4*6 SCREW	11/6	M5 SPRING MOTOR
10/7	GUIDE RAIL BRACKET RIGHT SUPPORT	11/7	M5*20 SCREW
.0/8	GUIDE RAIL BRACKET LEFT SUPPORT	11/8	φ12 CONNECTION BUSHION
.0/9	M5*12 SCREW	11/9	M5*6 SCREW
.0/10	M5 SPRING WASHER	11/10	φ12 Y SHAFT
10/11	M5 PLAIN WASHER	11/11	BEARING BRACKET
10/12	HK0808 NEEDLE BEARING	11/12	M5*16 SCREW
10/13	3M*20Φ10 PASSIVE PULLEY	11/13	NA4302 NEEDLE BEARING
.0/14	φ6 OPEN CIRCLIP	11/14	BEARING BUSHIONG
10/15	X-AXIS PASSIVE PULLEY BRACKET	11/15	BELT
10/16	X-AXIS PASSIVE PULLEY BRACKET ADJUSTING FIXING BRACKET	11/16	Y-AXIS LIMIT SENSOR
.0/10	A-AXIS PASSIVE POLLET BRACKET ADJUSTING FIXING BRACKET	11/17	M4 PLAIN WASHER
.0/17	M4 PLAIN WASHER	11/18	M4 SPRING WASHER
0/18	M4*16 SCREW	11/19	M4*8 SCREW
.0/19	M4 SPRING WASHER	11/20	M3*12 SCREW
10/20	M4*10 SCREW	11/21	M3 SPRING WASHER
	M4*8 SCREW	11/22	M3 PLAIN WASHER
0/22	PIN	11/23	BLET PLATE
.0/23	3M*20Ф8 PASSIVE PULLEY	11/24	M4*12 SCREW
0/24	M5*6 SCREW	11/25	GUIDE RAIL SLIDE BLOCK POSITION BRACKET
10/25	X-AXIS DRIVE MOTOR	11/26	420 STRAIGHT GUIDE RAIL
.0/26	X-AXIS MOTOR COVER	11/27	M5*12 SCREW
.0/27	X-AXIS PHOTO COUPLER BRACKET INSTALL SUPPORT	11/28	M5 PLAIN WASHER
.0/28	X-AXIS STOPPER	11/29	3m*33 PASSIVE PULLEY
.0/29	M3*6 SCREW	11/30	HK0808 NEEDLE BEARING
0/30	750 X-AXIS GUIDE RAIL	11/31	Φ6 OPEN CIRCLIP
	M3*10 SCREW	11/32	PIN
0/32	DOMESTIC X-AXIS EMBROIDERY FRAME LEFT SUPPORT	11/33	TENSION WHEEL BRACKET
0/33	DOMESTIC X-AXIS EMBROIDERY FRAME RIGHT SUPPORT	11/34	M5 NUT
0/34	DRIVE POSITION BLOCK(LEFT)	11/35	4*6 SCREW
0/35	DRIVE POSITION BLOCK(RIGHT)	11/36	Y-AXIS STOPPER
0/36	SPRING PLATE	1-2,00	J. 7500 5. 517 EN
0/37	M3 PLAIN WASHER	1	
.0/38	M3*8 SCREW	1	
0/39	CONNECTION PLATE	1	
0/40	M3 SPRING WASHER	†	
0/41	M3*12 SCREW	†	
.0/42	X-AXIS DRIVE BLET PLATE(LOWER)	†	
.0/ 72	A TONO DITTO DELL'I L'ALE LO VVEIL)	4	




Butterfly BUTTERFLY BRAND SINGLE HEAD MACHINE PARTS BOOK


- 1. BUTTERFLY SINGLE-HEAD MACHINE, RANGING FROM 9 NEEDLES TO 15 NEEDLES, STANDARD TO CUSTOMIZED EMBROIDERY AREA... IS DEVIDED INTO 20 DIAGRAMS.
- 2. IN EACH DIAGRAM, ALL PARTS ARE INDICATED WITH A DIGITAL WHICH IS USED TO LOCATE IT IN THE PARTS BOOK.
- (FOR EXAMPLE, DIGRAM 5-NEEDLE BAR DRIVE COMPONENTS & PART 29, IT IS 5/29. Press CTRL+F AND INPUT 5/29, THE PART IS LOCATED.)
- 3. FILL UP THE AFTER-SALES APPLICATION FORM WITH REQUIRED INFORMATION AND SEND IT TO BUTTERFLY. THE APPLICATION FORM COULD BE FOUND RIGHT NEXT TO THE DIAGRAM FORM.

12、THRE	AD TENSION PARTS	16、CAP	DRIVE PARTS	
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME	
12/1	THREAD GUIDE ASM.(12 NEEDLES)	16/1	CAP DRIVE ASM.	
	M4*16 SCREW	16/2	M4*12 SCREW	
	4*12 SCREW	16/3	M4 PLAIN WASHER	
	INDICATOR	16/4	M5*12 SCREW	
	SENSOR BASEPLATE	16/5	M5 PLAIN WASHER	
	MATIC WINDING PARTS		BASE PARTS	
DIAGRAM/PART	NAME	DIAGRAM/PART	NAME	
13/1	WINDING ASM.	17/1	CAP BASE ASM.	
	RUBBER WASHER	18、CAP	FRAME PARTS	
13/3	BOBBIN			
13/4	M4*8 SCREW	DIAGRAM/PART	NAME	
14 ELEC	TRICAL CONTROL PARTS	18/1	CAP FRAME ASM.	
DIAGRAM/PART	NAME		EAD SUPPORT	
14/1	MACHINE HEAD BACK CASE	DIAGRAM/PART	NAME	
	M4*6 SCREW	19/1	THREAD STAND BASEPLATE	
	M5*10 SCREW	19/2	THREAD STAND COLUMN	
	POWER BASEPLATE ASM.			
	4*8 SCREW	19/3	NAIL	
	COMPUTER BASEPLATE ASM. A	19/4	M5 PLAIN WASHER	
. 1	COMPUTER BASEPLATE ASM. A	19/5	M5 SPRING WASHER	
	M4*10 SCREW	19/6	M5 NUT	
	POWER BOX ASM.	19/7 19/8	M4*10 SCREW M5*10 SCREW	
	4*25 SCREW	19/8 19/9	M12 PLAIN WASHER	
	RATE PLATE	19/10	THREAD TENSION ASM.	
15\ 01 L1	AAILILAIL	19/11	M4 PLAIN WASHER	
DIAGRAM/PART	NAME	19/12	BUSHING	
15/1	COMPUTER MONITOR SUPPORT BOARD	19/13	M6*12 SCREW	
15/2	COMPUTER MONITOR CONNECTION BOARD B	19/14	THREAD STAND SUPPORT A	
15/3	M4*10 SCREW	19/15	THREAD STAND SUPPORT B	
	M5*10 SCREW	19/16	THREAD STAND SUPPORT C	
15/5	COMPUTER	19/17	THREAD STAND SUPPORT D	
		19/18	THREAD STAND SUPPORT E	
		19/19	THREAD STAND SUPPORT F	
		19/20	PLASTIC TUBE BUSHING	
		19/21	COPPER TUBE BUSHING	
		19/22	TUBE	
		20、EMBROIDERY FRAME		
		DIAGRAM/PART	NAME	
		20/1	X-AXIS FRAME	
		20/2	Y-AXIS FRAME	
		20/3	WOOL TOP(SHORT)	
		20/4	WOOL TOP(LONG)	
		20/5	FRAME ANGLE IRON	
		20/6	M6*12 SCREW	


1. FRAME AND TABLE COMPONENTS




2 ROTARY HOOK BOX




3、THREAD CUT COMPONENTS




4、MACHINE HEAD




5. NEEDLE BAR DRIVE COMPONENTS



6、UPPER THREAD HOLDER SETS




7、COLOR CHANGE COMPONENTS




8 NEEDLE BAR BRACKET (1)


9、NEEDLE BAR BRACKET (2)




10 X-AXIS DRIVE COMPONENTS




11 Y-AXIS DRIVE COMPONENTS




12. THREAD TENSION COMPONENTS




13. AUTOMATIC WINDING COMPONENTS




14 ELECTRICAL CONTROL COMPONENTS




15 OPERATE PLATE



16 CAP DRIVE COMPONENTS




17、CAP BASE COMPONENTSS



18 CAP FRAME COMPONENTS

19、THREAD SUPPORT



20 EMBROIDERY FRAME

BUTTERFLY BRAN	ID SINGLE HEAD MACHIN	IE PARTS BOOK
CONTRACT NO:		
APPLICANT:		n 44 61 °
APPLICATION DATE:		Butterfly
DIAGRAM/PART.	QUANTITY	REMARKS
	<u> </u>	
EXTRA INFORMATION (IF YOU HAVE A	NY):	
·	•	

